HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Louisville and Nashville Railroad,
Union Station
1000 West Broadway
Louisville
Jefferson County
Kentucky

HABS No. KY-152

Documentation: 8 ext. photos (1979)

3 int. photos (1979)

1 photocopy of aerial photograph (n.d.)

7 data pages (1974, 1981)

Jack Boucher, Photographer August 1979

KY-152-1 NORTH (FRONT) ELEVATION, FROM NORTHWEST

KY-152-2 WEST (SIDE) ELEVATION, FROM NORTHWEST

KY-152-3 EAST (SIDE) AND SOUTH (REAR) ELEVATIONS

KY-152-4 SOUTH (REAR) ELEVATION

KY-152-5 VIEW OF FREIGHT BUILDING, TO WEST OF THE STATION, FROM SOUTHWEST

KY-152-6 VIEW OF FRONT CANOPY, FROM NORTHWEST

KY-152-7 DETAIL OF TYPICAL CAST-IRON COLUMN, LOCATED IN THE TRAIN SHED, FROM SOUTH

KY-152-8 DETAIL OF CAST-IRON FENCE, LOCATED WEST OF THE STATION

KY-152-9 GENERAL VIEW OF WAITING ROOM, FROM SOUTHEAST

KY-152-10 VIEW OF SECOND FLOOR, WEST WALL, FROM SOUTHWEST

KY-152-11 DETAIL OF STAINED GLASS WINDOWS, NORTH END OF WAITING ROOM, SECOND FLOOR, FROM SOUTHEAST

PHOTOCOPY:

KY-152-12 AERIAL VIEW OF STATION.

Please credit: Louisville and Nashville Railroad Company/Family

Lines Rail System Archives

HISTORIC AMERICAN BUILDINGS SURVEY

HABS KY, 50-LOUVI, 23-

INDEX TO PHOTOGRAPHS

ADDENDUM TO
LOUISVILLE AND NASHVILLE RAILROAD, UNION STATION
(UNION STATION)
1000 West Broadway
Louisville
Jefferson County
Kentucky

HABS No. KY-152

KY-152-1 through KY-152-12 were transmitted to the Library of Congress.

INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Jack Boucher, Photographer, August 1979

KY-152-13 (CT)

DETAIL OF STAINED GLASS WINDOWS, NORTH END OF WAITING ROOM, SECOND FLOOR, FROM SOUTHEAST